



#10773

2" x 20" Coated Belt

Dense, blocky grain well suited for general purpose grinding and stock removal. Airfile belts easily reach narrow areas inaccessible by discs or wheels. Durable use on ferrous, non-ferrous, stainless steels, alloys and non-metallics.

Wide belts fit a wide range of stationary equipment for high production processing. Greater surface area and longer life with consistent finishing qualities. Dense, blocky grain well suited for general purpose grinding and stock removal. Durable use on ferrous, non-ferrous, stainless steels, alloys and non-metallics.